

**Table 3-6**

**Number of alive treatment (spillbay exposed) and control (released in discharge) chinook salmon held and remaining alive at 48 h for survival estimation at Bonneville Dam, October 1995.**

<b>Location</b>	<b>Number Released</b>	<b>Number Held</b>	<b>Number Alive (48 h)</b>
Spillbay 4: Flow Deflector (treatment)	280	278	276
Spillbay 2: No Flow Deflector (treatment)	280	269	269
Controls for spillbays	280	269	267